

# POTASH FELDSPAR

## **SPECIFICATION:**

Elements	Range (%)
SiO <sub>2</sub>	65 – 70
Al <sub>2</sub> O <sub>3</sub>	15 – 20
K <sub>2</sub> O	9 – 11
Na <sub>2</sub> O	2 – 3



## **PHYSICAL PROPERTIES :**

Appearance	White to light pink powder
Mesh Size	200 – 300 mesh
Loss on Ignition	1.50 %max
Moisture Content	0.5% max

## **APPLICATION:**

Welding electrode flux coatings , ceramic, glass, and paint industries.

## **PACKAGING:**

Bags - 25 & 50 kgs

## **STORAGE:**

Store in dry, well-ventilated area away from moisture.

## **SAFETY & HANDLING:**

1. Non-toxic but fine dust may cause irritation.
2. Use personal protective equipment (mask, gloves).