QUARTZ POWDER

SPECIFICATION:

| Elements | Range (%) |
|------------------|-----------|
| SiO ₂ | 98 min |
| Fe | 0.2 max |



PHYSICAL PROPERTIES:

| Appearance | White powder |
|-------------------------|--------------|
| Mesh Size | 300 mesh |
| Loss on Ignition | 0.5% max |
| Moisture Content | 0.5% max |

APPLICATION:

Welding electrode flux coatings, glass manufacturing, ceramics and other industrial applications.

PACKAGING:

Bags - 25 & 50 kgs

STORAGE:

Store in dry, well-ventilated area away from moisture.

SAFETY & HANDLING:

- 1. Non-toxic but fine dust may cause irritation.
- 2. Use personal protective equipment (mask, gloves).